State of Utah
DEPARTMENT OF NATURAL RESOURCES
Division of Oil, Gas & Mining

MICHAEL R. STYLER
Executive Director

JOHN R. BAZA
Division Director

Inspection Report
Minerals Regulatory Program
January 31, 2006

Supervisor _____

Mine Name: Grouse Creek Mountain
Operator Name: Bonneville Quarries, Inc.

Inspector(s): Lynn Kunzler
Other Participants: Bill Bown, Operator
Mine Status: Active

Permit number: S/003/031
Inspection Date: November 02, 2005
Time: 11:30 am

Weather:

Elements of Inspection	Evaluated	Comment	Enforcement
1. Permits, Revisions, Transfer, Bonds	☐	☐	☐
2. Public Safety (shafts, adits, trash, signs, highwalls)	☐	☐	☐
3. Protection of Drainages	☐	☐	☐
4. Roads (maintenance, surfacing, dust control, safety)	☒	☒	☐
5. Concurrent Reclamation	☐	☐	☐
6. Erosion Control	☒	☒	☐
7. Backfilling/Grading (trenches, pits, roads, highwalls, shafts, drill holes)	☐	☐	☐
8. Water Impoundments	☐	☐	☐
9. Soils	☐	☐	☐
10. Revegetation	☐	☐	☐
11. Air Quality	☒	☒	☐
12. Other	☐	☐	☐

Purpose of Inspection:

This inspection was done to document site conditions while in the area

Inspection Summary:

One goal of this inspection trip was to have Mr. Bown sign the transfer documents for the Green Beetle permit (S/003/017). This site was one of 3 sites that it was reported by others that Mr. Bown may be located. Mr. Bown was located at this site and signed the transfer forms so the Division can complete this action.

4, 6, & 11. This site is active, Mr. Bown has been working around the clock to finish an order before winter stops the work at this quarry. At the time of this inspection, sufficient stone had been palletted, and was awaiting shipping off site - He expected to finish by the end of the day . The access road shows signs of wear, but otherwise are not eroding or contributing to fugitive dust in the area. Road surface was damp at the time of this inspection. The area from which the stone had been quarried was a tallus slope - no soil disturbance or dust problems in this area. With 100 percent ground cover by rock, no erosion was taking place as well.

Conclusions and Recommendations:

The area appears to be in compliance - continue to monitor this site when in the area.

Inspector's Signature _____   **Date:** 1-31-06

LK:jb

O:\M003-BoxElder\M0030031-GrouseCreekQuarry\inspections\insp-11022005a.doc